

MACHINE SERVICE BULLETIN NO. 130

SUBJECT: 37-671 Crank Handle for
MA Model ~~37-671 Crank Handle for
MA Model~~

DATE: April 8, 1932

TO ALL OFFICES:

On most installations of machines crank handles are not supplied for hand operation. This results in an over-supply of these assemblies accumulating in District Offices.

Each office should carry a sufficient number for its needs and the excess should be returned to Orange.

As these parts were supplied to all offices without charge, they being a part of the original shipment of each machine, no credit can be given for the amount returned.

We would greatly appreciate the cooperation of each District Manager inventorying this surplus and instructing his Service Department to forward to us promptly, any of these assemblies which are in excess of his needs.

We would also suggest that you place this matter in your follow up file and take a similar inventory every three months.



General Service Manager

FMS:LJ

881 .00 MITALING SERVICES UNITED

Mr. B. P. James,
Toledo, Ohio.

Scal 8 1179A DATE

TO ALL OFFICES:


-que for eis selfied knys senidom to anotellstani taom no
to vifqua-revo na ni etuas alit. noitrisgo bnsd noh beily
. ayslalit of gulfisumood seilmeasa cred

abesn ati for iit fnciatis a vifla bnsda esillie doak
. cred of benifit ed bnsda asexa and his

agralo fuddiw asoflo lls of beilgus evow crifl esell an
enidom noh to fnciatis fashigto ed to fsl a yntd cred
benifit fnciatis ed for novig ed nso vifla on

colatid More to noitrisgoob ed etasidetid appesidz bnsda ed
etisidetid ati pafciatid bnsda etuas fnciatis fashigto
kikid fnciatis to yus, ayslalit of fnciatis ed to
abesn aid to asexa ni eis hold

for ayslalit fnciatis ed to fnciatis fashigto ed to
abesn aid to asexa ni eis hold


General Service Member

LI:EMT